




ANEXA 2

**Depozit**  
 Alimentare improvizata, din  
 lactorbar printr-un prelungitor  
 3x2,5mm  
 Instalatie inechita, necesita  
 refacere completa


**Capela Greco Catolica**  
 Instalatie vechi, montaj ingropat  
 tub Bergman  
 Conductorii aluminiu tip AFY  
 Conductor pamantare numai pt.  
 circuit prize  
 Confortizare cu contor  
 Asoc.Handicapator  
 Instalatie inechita, necesita  
 refacere completa










PTA TRANDAFIRU









**E314.00**  
 s=14,85 mp  
 p=16,30 ml  
 h=3,05 m

**E313.00**  
 s=9,84 mp  
 p=14,44 ml  
 h=3,05 m

**E315.00**  
 s=16,35 mp  
 p=18,08 ml  
 h=3,05 m

**E316.00**  
 s=6,14 mp  
 p=11,80 ml  
 h=3,05 m

**E316.01**  
 s=5,84 mp  
 p=9,84 ml  
 h=3,05 m

**E316.02**  
 s=15,40 mp  
 p=16,24 ml  
 h=3,05 m

**E211.00**

**E316.03**  
 s=1,27 mp  
 p=4,54 ml  
 h=3,05 m

**E211.00**  
 s=5,31 m  
 p=9,30 n  
 h=3,00 m

51R-30x16

19TR-30x15,81

3TR-30x15,81

hp=95

hp=80

hp=174

hp=107

